

Exterior Siding



We had issues with flickers pecking through the cedar siding and building nests inside the insulation of our

walls. They return year after year and before we knew it we had multiple holes in the siding and I found at least three nests when I tore out the old walls and insulation. The dried out cedar siding attracted them. So I decided to replace it with cement board panels and to add Siga exterior membrane. (Majvest) I replaced damaged foil type polyiso boards. Then I added a rain screen layer. This is an industrial practice that is also good for homes. I stuffed stainless steel bug proofing at the eaves and foundation to eliminate wasps behind the siding and used James Hardie cement board panels for their sustainability.

