



National Gypsum Sustainable Materials Data Sheet

Materials and Resources - Recycled Content

Product Name	Manufacturing Location	Post Consumer	Pre Consumer	Materials Cost
1/2" Gold Bond e ² XP Extended Exposure Interior Extreme	Phoenix, AZ	0%	0%	
5/8" Gold Bond e ² XP Extended Exposure Interior Extreme	Phoenix, AZ	0%	0%	
1" Gold Bond e ² XP Extended Exposure Shaftliner	Medicine Lodge, KS	0%	0%	
1/2" Gold Bond e ² XP Extended Exposure Tile Backer	Medicine Lodge, KS	0%	0%	
5/8" Gold Bond e ² XP Extended Exposure Tile Backer	Medicine Lodge, KS	0%	0%	
1/2" Gold Bond XP Gypsum Board	Medicine Lodge, KS	5%	3%	
1/2" Gold Bond XP Fire-Shield C Gypsum Board	Rotan, TX	5%	3%	
5/8" Gold Bond XP Fire-Shield Gypsum Board	Medicine Lodge, KS	5%	3%	
1" Gold Bond Fire-Shield Shaftliner XP	Waukegan, IL	5%	40%	
5/8" Gold Bond Hi-Abuse XP Gypsum Board	Rotan, TX	5%	3%	
5/8" Gold Bond Hi-Impact XP Gypsum Board	Rotan, TX	5%	3%	
1/2" Gold Bond SoundBreak XP Gypsum Board	Medicine Lodge, KS	5%	3%	
5/8" Gold Bond SoundBreak XP Gypsum Board	Medicine Lodge, KS	5%	3%	
1/2" Gold Bond Regular Gypsum Board	Medicine Lodge, KS	5%	3%	
1/2" Gold Bond Fire-Shield C Gypsum Board	Medicine Lodge, KS	5%	3%	
1/2" Gold Bond Foilback Gypsum Board	Rotan, TX	5%	3%	
5/8" Gold Bond Fire-Shield C Gypsum Board	Rotan, TX	5%	3%	
5/8" Gold Bond Fire-Shield Gypsum Board	Medicine Lodge, KS	5%	3%	
5/8" Gold Bond Fire-Shield FoilbackGypsum Board	Rotan, TX	5%	3%	
1" Gold Bond Fire-Shield Shaftliner	Waukegan, IL	5%	40%	
1/2" Gold Bond High Strength Ceiling Board	Medicine Lodge, KS	5%	3%	
1/4" Gold Bond Gypsum Board	Medicine Lodge, KS	5%	3%	
1/4" Gold Bond Gypsum High Flex Board	Medicine Lodge, KS	5%	3%	
3/8" Gold Bond Gypsum Board	Medicine Lodge, KS	5%	3%	
1/2" Gold Bond e ² XP Extended Exposure Gypsum Sheathing	Medicine Lodge, KS	0%	0%	
5/8" Gold Bond e ² XP Extended Exposure Gypsum Sheathing	Medicine Lodge, KS	0%	0%	
1/2" Gold Bond Gypsum Sheathing	Rotan, TX	5%	3%	
5/8" Gold Bond Fire-Shield Jumbo Gypsum Sheathing	Rotan, TX	5%	3%	
1/2" Gold Bond Exterior Soffit Board	Medicine Lodge, KS	5%	3%	
5/8" Gold Bond Exterior Soffit Board	Medicine Lodge, KS	5%	3%	
1/2" Gold Bond Gridstone Ceiling Panels	Rotan, TX	5%	3%	
1/2" Gold Bond Gridstone CleanRoom Ceiling Panels	Rotan, TX	5%	3%	
5/16"Gold Bond Gridstone Hi-Strength Ceiling Panels	Rotan, TX	5%	3%	
1/2" Gold Bond Regular Kal-Kore Plaster Base	Medicine Lodge, KS	5%	3%	

Corporate Headquarters
 National Gypsum Company
 2001 Rexford Road
 Charlotte, NC 28211
 Phone: (704) 365-7300
 Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
 Phone: (800) NATIONAL
 (800) 628-4662
 Fax: (800) FAX-NGC1
 (800) 329-6421





National Gypsum Sustainable Materials Data Sheet

Product Name	Manufacturing Location	Post Consumer	Pre Consumer	Materials Cost
5/8" Gold Bond Kal-Kore Fire-Shield C Plaster Base	Fort Dodge, IA	5%	4%	
5/8" Gold Bond Kal-Kore Fire-Shield	Medicine Lodge, KS	5%	3%	
5/8" Gold Bond Fire Shield Kal-Kore Hi-Abuse Plaster Base	Waukegan, IL	5%	40%	
Gold Bond Two-Way Hardwall Gypsum Plaster	Shoals, IN	0%	0%	
Gold Bond Gypsolite Plaster	Fort Dodge, IA	0%	0%	
Gold Bond Super-White Gauging Plaster	Medicine Lodge, KS	0%	0%	
Gold Bond Super-White Moulding Plaster	Medicine Lodge, KS	0%	0%	
Gold Bond Kal-Kote Plaster Base	Fort Dodge, IA	0%	0%	
Gold Bond Kal-Kote Smooth Finish Plaster	Medicine Lodge, KS	0%	0%	
Gold Bond Kal-Kote Texture Finish Plaster	Fort Dodge, IA	0%	0%	
Gold Bond Uni Kal Veneer Plaster	Medicine Lodge, KS	0%	0%	
Gold Bond X-Kalibur Veneer Plaster	Medicine Lodge, KS	0%	0%	
All Purpose, Lite, Lite-Blue, Multi Use, Dust-Tech Ready Mix Joint Compound	Long Beach, CA	0%	0%	
XP Dust-Tech Ready Mix Joint Compound	Long Beach, CA	0%	0%	
Quick Set, Quick Set Lite Setting Compounds	Rensselaer, IN	0%	0%	
Paper Tape, Mesh Tape	Rensselaer, IN	0%	0%	

Gold Bond Gypsum Board

Gypsum board face and back paper is made of 100% post-consumer recycled content.

Gypsum board recycled content varies by manufacturing location.

Scrap from gypsum board manufacturing is recycled back into the process.

ProForm Drywall Finishing Products do not have recycled content; however, they may contribute in other categories covered in this report.

Report results are based on current National Gypsum distribution plan and manufacturing location capabilities. Gold Bond Gypsum Board products with higher recycled content may be available for projects in Northeastern and Mid Atlantic states. Please contact your local National Gypsum Sales Representative or call 1-800-NATIONAL for assistance. National Gypsum reserves the right to determine the plant from which products will be shipped.

Corporate Headquarters
 National Gypsum Company
 2001 Rexford Road
 Charlotte, NC 28211
 Phone: (704) 365-7300
 Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
 Phone: (800) NATIONAL
 (800) 628-4662
 Fax: (800) FAX-NGC1
 (800) 329-6421





National Gypsum Sustainable Materials Data Sheet

Materials and Resources - Regional Materials

Product Name	Manufacturing Location		Extraction Point Location		%	Materials Cost
	City, State	Distance	City, State	Distance		
1/2" Gold Bond e ² XP Extended Exposure Interior Extreme	Phoenix, AZ	> 500 mi.	Winkelman, AZ	> 500 mi.	95%	
5/8" Gold Bond e ² XP Extended Exposure Interior Extreme	Phoenix, AZ	> 500 mi.	Winkelman, AZ	> 500 mi.	95%	
1" Gold Bond e ² XP Extended Exposure Shaftliner	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond e ² XP Extended Exposure Tile Backer	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
5/8" Gold Bond e ² XP Extended Exposure Tile Backer	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond XP Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond XP Fire-Shield C Gypsum Board	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
5/8" Gold Bond XP Fire-Shield Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1" Gold Bond Fire-Shield Shaftliner XP	Waukegan, IL	> 500 mi.	Tawas, MI Pleasant Prairie, WI	> 500 mi. > 500 mi.	55% 40%	
5/8" Gold Bond Hi-Abuse XP Gypsum Board	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
5/8" Gold Bond Hi-Impact XP Gypsum Board	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
1/2" Gold Bond SoundBreak XP Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
5/8" Gold Bond SoundBreak XP Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond Regular Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond Fire-Shield C Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond Foilback Gypsum Board	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
5/8" Gold Bond Fire-Shield C Gypsum Board	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
5/8" Gold Bond Fire-Shield Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
5/8" Gold Bond Fire-Shield FoilbackGypsum Board	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	

Corporate Headquarters
 National Gypsum Company
 2001 Rexford Road
 Charlotte, NC 28211
 Phone: (704) 365-7300
 Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
 Phone: (800) NATIONAL
 (800) 628-4662
 Fax: (800) FAX-NGC1
 (800) 329-6421





National Gypsum Sustainable Materials Data Sheet

Product Name	Manufacturing Location		Extraction Point Location		%	Materials Cost
	City, State	Distance	City, State	Distance		
1" Gold Bond Fire-Shield Shaftliner	Waukegan, IL	> 500 mi.	Tawas, MI	> 500 mi.	55%	
			Pleasant Prairie, WI	> 500 mi.	40%	
1/2" Gold Bond High Strength Ceiling Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/4" Gold Bond Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/4" Gold Bond Gypsum High Flex Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
3/8" Gold Bond Gypsum Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond e ² XP Extended Exposure Gypsum Sheathing	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
5/8" Gold Bond e ² XP Extended Exposure Gypsum Sheathing	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond Gypsum Sheathing	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
5/8" Gold Bond Fire-Shield Jumbo Gypsum Sheathing	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
1/2" Gold Bond Exterior Soffit Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
5/8" Gold Bond Exterior Soffit Board	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
1/2" Gold Bond Gridstone Ceiling Panels	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
1/2" Gold Bond Gridstone CleanRoom Ceiling Panels	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
5/16" Gold Bond Gridstone Hi-Strength Ceiling Panels	Rotan, TX	> 500 mi.	Rotan, TX	> 500 mi.	95%	
1/2" Gold Bond Regular Kal-Kore Plaster Base	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
5/8" Gold Bond Kal-Kore Fire-Shield C Plaster Base	Fort Dodge, IA	> 500 mi.	Fort Dodge, IA	> 500 mi.	95%	
5/8" Gold Bond Kal-Kore Fire-Shield	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	95%	
5/8" Gold Bond Fire Shield Kal-Kore Hi-Abuse Plaster Base	Waukegan, IL	> 500 mi.	Tawas, MI	> 500 mi.	55%	
			Pleasant Prairie, WI	> 500 mi.	40%	
Gold Bond Two-Way Hardwall Gypsum Plaster	Shoals, IN	> 500 mi.	Shoals, IN	> 500 mi.	98%	

Corporate Headquarters
 National Gypsum Company
 2001 Rexford Road
 Charlotte, NC 28211
 Phone: (704) 365-7300
 Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
 Phone: (800) NATIONAL
 (800) 628-4662
 Fax: (800) FAX-NGC1
 (800) 329-6421





National Gypsum Sustainable Materials Data Sheet

Product Name	Manufacturing Location		Extraction Point Location		%	Materials Cost
	City, State	Distance	City, State	Distance		
Gold Bond Gypsolite Plaster	Fort Dodge, IA	> 500 mi.	Fort Dodge, IA	> 500 mi.	85%	
Gold Bond Super-White Gauging Plaster	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	98%	
Gold Bond Super-White Moulding Plaster	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	98%	
Gold Bond Kal-Kote Plaster Base	Fort Dodge, IA	> 500 mi.	Fort Dodge, IA	> 500 mi.	50%	
Gold Bond Kal-Kote Smooth Finish Plaster	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	50%	
Gold Bond Kal-Kote Texture Finish Plaster	Fort Dodge, IA	> 500 mi.	Fort Dodge, IA	> 500 mi.	38%	
Gold Bond Uni Kal Veneer Plaster	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	85%	
Gold Bond X-Kalibur Veneer Plaster	Medicine Lodge, KS	395 mi.	Sun City, KS	375 mi.	85%	
All Purpose, Lite, Lite-Blue, Multi Use, Dust-Tech Ready Mix Joint Compound	Long Beach, CA	> 500 mi.	N/A, NA	> 500 mi.	95%	
XP Dust-Tech Ready Mix Joint Compound	Long Beach, CA	> 500 mi.	N/A, NA	> 500 mi.	95%	
Quick Set, Quick Set Lite Setting Compounds	Rensselaer, IN	> 500 mi.	N/A, NA	> 500 mi.	95%	
Paper Tape, Mesh Tape	Rensselaer, IN	> 500 mi.	N/A, NA	> 500 mi.	100%	

Manufacturing plant and extraction locations are provided to assist the report preparer in determining the contribution to Regional Materials credits. Mileage calculations reflect the distances from both manufacturing and extraction locations to the project address provided by the report preparer. The National Gypsum Green Product Score (GPS) tool accesses Google Maps to determine these calculations.

Mileage reflects the great circle distance between the project address and the manufacturing and extraction locations. If mileage is not shown, it is not known or unavailable due to multiple supplier locations.

For purposes of calculating credits for products that qualify for Regional Materials, gypsum board is comprised of 95% gypsum. Paper and additional materials come from multiple locations.


USGBC CIR – USGBC has determined that in place of actual miles in the submittal template, a letter of verification from the manufacturer will satisfy all applicable and current rating systems regarding the achievement of MRc5. The GPS report which can be generated from this site serves as the National Gypsum letter of verification.



National Gypsum Sustainable Materials Data Sheet

Materials and Resources - Regional Materials Map

The Map illustrates distances shown on the previous table with the project address at the center of the 500 mile radius.



Corporate Headquarters
 National Gypsum Company
 2001 Rexford Road
 Charlotte, NC 28211
 Phone: (704) 365-7300
 Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
 Phone: (800) NATIONAL
 (800) 628-4662
 Fax: (800) FAX-NGC1
 (800) 329-6421





National Gypsum Sustainable Materials Data Sheet

Materials and Resources - Product Certifications

Product Name	GREENGUARD	GREENGUARD Children & Schools	CHPS	Mold Resistance	Material Cost
1/2" Gold Bond e ² XP Extended Exposure Interior Extreme	Yes	Yes	Yes	ASTM D 3273 - 10	
5/8" Gold Bond e ² XP Extended Exposure Interior Extreme	Yes	Yes	Yes	ASTM D 3273 - 10	
1" Gold Bond e ² XP Extended Exposure Shaftliner	No	No	No	ASTM D 3273 - 10	
1/2" Gold Bond e ² XP Extended Exposure Tile Backer	Yes	Yes	Yes	ASTM D 3273 - 10	
5/8" Gold Bond e ² XP Extended Exposure Tile Backer	Yes	Yes	Yes	ASTM D 3273 - 10	
1/2" Gold Bond XP Gypsum Board	Yes	Yes	Yes	ASTM D 3273 - 10 G21 - 0	
1/2" Gold Bond XP Fire-Shield C Gypsum Board	Yes	Yes	Yes	ASTM D 3273 - 10 G21 - 0	
5/8" Gold Bond XP Fire-Shield Gypsum Board	Yes	Yes	Yes	ASTM D 3273 - 10 G21 - 0	
1" Gold Bond Fire-Shield Shaftliner XP	No	No	No	ASTM D 3273 - 10 G21 - 0	
5/8" Gold Bond Hi-Abuse XP Gypsum Board	Yes	Yes	Yes	ASTM D 3273 - 10 G21 - 0	
5/8" Gold Bond Hi-Impact XP Gypsum Board	Yes	Yes	Yes	ASTM D 3273 - 10 G21 - 0	
1/2" Gold Bond SoundBreak XP Gypsum Board	Yes	Yes	Yes	ASTM D 3273 - 10 G21 - 0	
5/8" Gold Bond SoundBreak XP Gypsum Board	Yes	Yes	Yes	ASTM D 3273 - 10 G21 - 0	
1/2" Gold Bond Regular Gypsum Board	Yes	Yes	Yes		
1/2" Gold Bond Fire-Shield C Gypsum Board	Yes	Yes	Yes		
1/2" Gold Bond Foilback Gypsum Board	Yes	Yes	Yes		
5/8" Gold Bond Fire-Shield C Gypsum Board	Yes	Yes	Yes		
5/8" Gold Bond Fire-Shield Gypsum Board	Yes	Yes	Yes		
5/8" Gold Bond Fire-Shield Foilback Gypsum Board	Yes	Yes	Yes		
1" Gold Bond Fire-Shield Shaftliner	No	No	No		
1/2" Gold Bond High Strength Ceiling Board	No	No	No		
1/4" Gold Bond Gypsum Board	Yes	Yes	Yes		

Corporate Headquarters
 National Gypsum Company
 2001 Rexford Road
 Charlotte, NC 28211
 Phone: (704) 365-7300
 Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
 Phone: (800) NATIONAL
 (800) 628-4662
 Fax: (800) FAX-NGC1
 (800) 329-6421





National Gypsum Sustainable Materials Data Sheet

Product Name	GREENGUARD			Mold Resistance	Material Cost
	GREENGUARD	Children & Schools	CHPS		
1/4" Gold Bond Gypsum High Flex Board	No	No	No		
3/8" Gold Bond Gypsum Board	Yes	Yes	Yes		
1/2" Gold Bond e ² XP Extended Exposure Gypsum Sheathing	No	No	No	ASTM D 3273 - 10	
5/8" Gold Bond e ² XP Extended Exposure Gypsum Sheathing	No	No	No	ASTM D 3273 - 10	
1/2" Gold Bond Gypsum Sheathing	No	No	No		
5/8" Gold Bond Fire-Shield Jumbo Gypsum Sheathing	No	No	No		
1/2" Gold Bond Exterior Soffit Board	No	No	No		
5/8" Gold Bond Exterior Soffit Board	No	No	No		
1/2" Gold Bond Gridstone Ceiling Panels	Yes	Yes	Yes		
1/2" Gold Bond Gridstone CleanRoom Ceiling Panels	Yes	Yes	Yes		
5/16" Gold Bond Gridstone Hi-Strength Ceiling Panels	Yes	Yes	Yes		
1/2" Gold Bond Regular Kal-Kore Plaster Base	No	No	No		
5/8" Gold Bond Kal-Kore Fire-Shield C Plaster Base	No	No	No		
5/8" Gold Bond Kal-Kore Fire-Shield	No	No	No		
5/8" Gold Bond Fire Shield Kal-Kore Hi-Abuse Plaster Base	No	No	No		
Gold Bond Two-Way Hardwall Gypsum Plaster	No	No	No		
Gold Bond Gypsolite Plaster	No	No	No		
Gold Bond Super-White Gauging Plaster	No	No	No		
Gold Bond Super-White Moulding Plaster	No	No	No		
Gold Bond Kal-Kote Plaster Base	No	No	No		
Gold Bond Kal-Kote Smooth Finish Plaster	No	No	No		
Gold Bond Kal-Kote Texture Finish Plaster	No	No	No		
Gold Bond Uni Kal Veneer Plaster	No	No	No		
Gold Bond X-Kalibur Veneer Plaster	No	No	No		
All Purpose, Lite, Lite-Blue, Multi Use, Dust-Tech Ready Mix Joint Compound	Yes	No	No		
XP Dust-Tech Ready Mix Joint Compound	Yes	Yes	Yes	ASTM D 3273 - 10	
Quick Set, Quick Set Lite Setting Compounds	Yes	Yes	Yes		
Paper Tape, Mesh Tape	No	No	No		

Corporate Headquarters
 National Gypsum Company
 2001 Rexford Road
 Charlotte, NC 28211
 Phone: (704) 365-7300
 Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
 Phone: (800) NATIONAL
 (800) 628-4662
 Fax: (800) FAX-NGC1
 (800) 329-6421





National Gypsum Sustainable Materials Data Sheet



Third party certifications may contribute to additional credits such as Indoor Air Quality and Innovation & Design.

All ProForm Brand joint treatment ready-mixed products contain <2g/L of VOC content.



Corporate Headquarters
National Gypsum Company
2001 Rexford Road
Charlotte, NC 28211
Phone: (704) 365-7300
Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
Phone: (800) NATIONAL
(800) 628-4662
Fax: (800) FAX-NGC1
(800) 329-6421





National Gypsum Sustainable Materials Data Sheet

General Notes

The product information provided by National Gypsum to generate each report relates only to products and product content that National Gypsum would ship after it receives and accepts an order. It is the responsibility of the gypsum distributor and drywall contractor working on a particular project to fulfill applicable credits requirements for that project. While National Gypsum will fulfill orders from its customers for products that may be intended by the customer to be placed on a particular job or project, National Gypsum cannot control which of its products are actually placed on the jobsite after shipment.

The GPS report is generated based on the product and project information provided by the report preparer and is accurate at the time the report is generated. National Gypsum reserves the right to change its product content or specifications at any time, without notice. To assure the most accurate sustainable materials data, a report should be generated at the time the product order is finally placed, just prior to product shipment.

Total Material Cost is provided by the report preparer and does not reflect a unit cost for materials.

For additional information, please contact your National Gypsum sales representative.
For technical product information, please contact 1-800-NATIONAL.

Trademarks

The product names referenced in the Green Product Score report are trademarks and brands owned by National Gypsum Properties, LLC:

Durasan®
e2XP®
e2XP® Interior Extreme™
Dust-Tech™
Fire-Shield®
Fire-Shield C™
Gold Bond®
Green Product Score™
Gridstone®

High Flex®
Hi-Abuse® XP®
Hi-Impact® XP®
Kal-Kore®
Kal-Kote®
National Gypsum®
PermaBase®
PermaBase Flex®
PermaBase® UltraBacker™

ProForm®
Shaftliner®
Shaftliner XP®
SoundBreak® XP®
ThermalCORE™
Quick Set™
XP®
1-800-NATIONAL®

Corporate Headquarters
National Gypsum Company
2001 Rexford Road
Charlotte, NC 28211
Phone: (704) 365-7300
Web: nationalgypsum.com
nationalgypsum.com/espanol

Technical Information
Phone: (800) NATIONAL
(800) 628-4662
Fax: (800) FAX-NGC1
(800) 329-6421

