Crawlspace Conditioned



Debris removed

The outside vent was closed and insulated.

Radiator and water pipes were insulated to R-7.



Vapor barrier caulked to walls

The radon pipe vents through the roof.

Conditioning the crawlspace is another LEED requirement; the debris was removed from the crawlspace. Reused billboard vinyl tarps were spread over the ground. Seams were taped and caulked to walls.



Outside vent removed

House air can be pulled through the crawlspace with a small circulating fan in the master bedroom closet.



Thick R-7 insulation on water pipes